
Seite 1 von 1 : Artikel 1 - 3 von 3

ArtikelNr. [1]	Artikel-Bezeichnung [2]	Preis incl.
R 443 [3]	Fuel sensor, second typ with one cable connection - 4 CV 1955 ->/Dauphine/Floride/Caravelle-Cabrio - 6/12 Volt [3]	58,00 €
R 1572 [4]	Fuel filter with non-return valve - 6 mm [4]	11,50 €
C 190/2 [5]	Carburater reapair-kit for Caravelle 1131 - SOLEX 32 PDIST - DITA [5]	38,00 €



[PDF Version](#) [6]

Source URL (retrieved on 2024-05-05

23:45):<https://www.schuetzenhofer.de/en/catalog/128?order=model&sort=desc>

Links

[1] <https://www.schuetzenhofer.de/en/catalog/128?order=model&sort=asc> [2] <https://www.schuetzenhofer.de/en/catalog/128?order=title&sort=asc> [3] <https://www.schuetzenhofer.de/en/content/fuel-sensor-second-typ-one-cable-connection-4-cv-1955-dauphinefloridecaravelle-cabrio-612> [4] <https://www.schuetzenhofer.de/en/content/fuel-filter-non-return-valve-6-mm> [5] <https://www.schuetzenhofer.de/en/content/carburater-reapair-kit-caravelle-1131-solex-32-pdist-dita> [6] <https://www.schuetzenhofer.de/en/printpdf/catalog/128?order=model&sort=desc>